

DEPARTMENT OF ECOLOGY -- TOXICS CLEANUP PROGRAM
INTEGRATED SITE INFORMATION SYSTEM--UST DATA SUMMARY AS OF 04/13/2009 FOR EPA

UST SITE INFORMATION

SITE ID: 8827

SOUTH SERVICE CENTER

3613 4TH AVE S

SEATTLE, WA 98134

PHONE #: (206) 386-4577

UBI: 178-048-953 001 0085

King

FACILITY SITE INFORMATION

FACILITY SITE ID: 2171

SOUTH SERVICE CENTER

3613 4TH AVE S

SEATTLE, WA 98108

Site Owner

Party ID: 622103 CITY OF SEATTLE
HARRIS MARTIN
700 FIFTH AVE STE 3300

() - UBI:
98124
SEATTLE WA

Site Operator

Party ID: 624687 FLEETS & FACILITIES
PO BOX 94689

() - UBI:
98124
SEATTLE WA

TANK NAME	INSTALLED	TANK MATERIAL	TANK CONSTRUCTION	PUMPING SYSTEM		
STATUS	CLOSED	PIPE MATERIAL	PIPE CONSTRUCTION	CP	SPILL	OVER
1	12/31/1964	Steel	Single Wall Tank			
Removed		Steel				
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Unleaded Gasoline		CAPACITY: 3000			
2	12/31/1964	Steel	Single Wall Tank			
Removed		Steel				
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Unleaded Gasoline		CAPACITY: 3000			
4	12/31/1964	Steel	Single Wall Tank			
Removed		Steel				
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Motor Oil		CAPACITY: 500			
5	12/31/1964	Steel	Single Wall Tank			
Removed		Steel				
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Motor Oil		CAPACITY: 500			
6	12/31/1964	Steel	Single Wall Tank			
Removed		Steel				
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Used Oil/Waste Oil		CAPACITY: 500			
A	12/31/1964					
Removed						
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Unleaded Gasoline		CAPACITY: 2500			
B	12/31/1964					
Removed						
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Unleaded Gasoline		CAPACITY: 2150			
D	12/31/1964					
Removed						
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Other Petroleum Sut		CAPACITY: 550			
E	12/31/1964					
Removed						
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Motor Oil		CAPACITY: 550			
FIVE	2/28/1989	Fiberglass Reinforced Plastic	Double Wall Tank	Suction System Pump Check Valve		
Removed	10/26/2005	Fiberglass	Double Wall Pipe	Yes	Yes	Yes
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Motor Oil		CAPACITY: 500			

DEPARTMENT OF ECOLOGY -- TOXICS CLEANUP PROGRAM
INTEGRATED SITE INFORMATION SYSTEM--UST DATA SUMMARY AS OF 04/13/2009 FOR EPA

TANK NAME	INSTALLED	TANK MATERIAL	TANK CONSTRUCTION	PUMPING SYSTEM		
STATUS	CLOSED	PIPE MATERIAL	PIPE CONSTRUCTION	CP	SPILL	OVER
FOUR	2/28/1989	Fiberglass Reinforced Plastic	Double Wall Tank	Suction System Pump Check Valve		
Removed	10/26/2005	Fiberglass	Double Wall Pipe	Yes	Yes	Yes
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Motor Oil		CAPACITY: 500			
ONE	3/1/1989	Fiberglass Reinforced Plastic	Double Wall Tank	Suction System Pump Check Valve		
Operational	10/26/2005	Fiberglass	Double Wall Pipe	Yes	Yes	Yes
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Unleaded Gasoline		CAPACITY: 4000			
SEVEN	12/12/2005	Steel Clad with Corrosion Resistant Compos	Double Wall Tank	Suction System Pump Check Valve		
Operational		Fiberglass	Double Wall Pipe	Yes	Yes	Yes
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Diesel		CAPACITY: 4000			
SIX	12/31/1983	Coated Steel	Single Wall Tank	Pressurized System		
Removed	10/26/2005	Fiberglass	Double Wall Pipe	Yes	Yes	Yes
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Diesel		CAPACITY: 2000			
THREE	2/28/1989	Fiberglass Reinforced Plastic	Double Wall Tank	Product Removed by Reclaimer		
Removed	10/26/2005	No Piping Attached to Tank	No Piping Attached to Tank	Yes	Yes	Yes
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Used Oil/Waste Oil		CAPACITY: 500			
TWO	3/1/1989	Fiberglass Reinforced Plastic	Double Wall Tank	Suction System Pump Check Valve		
Operational	10/26/2005	Fiberglass	Double Wall Pipe	Yes	Yes	Yes
COMPARTMENT DETAILS						
ID: 1	PRODUCT: Unleaded Gasoline		CAPACITY: 4000			

INSPECTION INFORMATION

INSPECTOR: OLSEN, RUSS

INSPECTION RESULT: Followup Required

INSPECTION TYPE: UST Compliance Inspection

INSPECTION DATE: 6/29/2006

INSPECTION METHOD: Field Visit

INSPECTION CONTACT: MARY YODER WILLIAMS

SOC INSPECTION RESULTS

SOC SPILL/OVERFILL/CORROSION: Yes - In Compliance

SOC RELEASE DETECTION: Yes - In Compliance

INSPECTION COMMENTS